

Date

No. 303 in builder's yard.

DATES held whi as per S

4th. When the ship was complete, and before the plating was finally coated or cemented..

5th. After the ship was launched and equipped

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

General Remarks (State quality of workmanship, &c.)

Workmans hip of good quality.

The Iron used in the construction of this vessel as well as the Mast has been carefully tested and found to be of good quality.

And is built in accordance with accompanying approved tracings as per Secretaries Lett. dated 9<sup>th</sup> 12<sup>th</sup> Feb and 20<sup>th</sup> June 1880.

Length of fore-castle 39 feet, of Bridge house 04 feet, of Wheel house 8 feet, Length of double bottom 21<sup>1</sup>/<sub>4</sub> <sup>feet</sup>. Capacity in tons 31<sup>1</sup>/<sub>4</sub>.

The double bottom was tested previous to launching and was found to be fairly tight, since that time

under beams, and Engine seat have been fitted

filled afloat the tanks were leaking at aft

the Engine seat, but the tanks have

Liverpool. Plans of pumping will be forwarded to

State if one, two, or three decked vessel, or if

How are the surfaces pres

I am of opin



© 2021 Lloyd's Register Foundation