

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING.

No. 4415

(Received at London Office, Lloyd's Register of Shipping)
RECEIVED
-1 JUN. 88

TESTS OF BOILER STEEL.

Tests of 4 Steel plates manufactured by The Steel Co. of Scotland of Glasgow for Boiler No. 4188 to be constructed by Messrs Hall Russell & Co. of Aberdeen for the S.S. "Dabulamengi".

Date first visit 23/5/88 last visit 30/5/88 No. of visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests Satisfactory
All cut from one plate

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
	Front Tube pl. 1 5/16	G. 183		399	.95	1.16	1.102	32.6	29.5	21	✓

W.P.
5/6/88

Fee £ : :

Expenses £ : :

£ : :

To be paid by

© 2021
J. J. Roberts
Surveyor, Lloyd's Register,
Glasgow
30/5/88