

REPORT of SURVEY for REPAIRS.

Rev. 25/2/50

No. 1405 Survey held at Aberdeen Date 23 February 1850
 on the Bug Emperor Master J. Dinnison
 Tonnage 264 Built at Aberdeen When built 1849
 By whom built W. Hood & Co Owners J. Dinnison & others
 Port belonging to Aberdeen Destined Voyage Whitby
 If Surveyed Afloat or in Dry Dock on Slip & afloat

Last Survey, No. 1363 Port Aberdeen Classed G A1

REPAIRS of Damage one Shift of plank under Males on Starboard side renewed with Red Oak & one in Topsides of Mahogany part of Main rail same side & one Rough tree Stanchion renewed

Present Condition of the

Decks	} <u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson	<u>do</u>	Pumps	<u>Two do</u>
Comings	} <u>Good</u>	Transoms, Pointers, and Crutches	<u>do</u>	Boats	<u>Two do</u>
Upper Deck Beams & Fastenings		Timbers of the Frame	<u>Good</u>	Masts, Yards, &c.	<u>Good & complete</u>
Lower Deck Beams & Fastenings	} <u>firm</u>	Keelsons	<u>do</u>	Sails	<u>full suit & a few spare good</u>
Planksheers	} <u>Good order</u>	Clamps and Shells	<u>do</u>	Anchors	No. of <u>2 B¹/₁₆ in & 2 Ridges</u>
Sheerstrakes		Ceiling	<u>do</u>	Cables	<u>B¹/₄ in complete</u>
Topsides		Rudder	<u>do</u>	Hawsers and Warps	<u>1 New & 3 Warps good</u>
Wales	} <u>do do</u>	Copper	When put on	Standing & Running Rigging	<u>good</u>
Plank (Bottom) and Counter					

General Observations and Opinion, This vessel is in the best of order & may remain as classed

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : :

Committee's Minute 26th Feb 1850

Character assigned G A1



© 2021

Lloyd's Register Foundation