

1.

Sent to Chief Surveyors

5-9-04

Received from Chief Surveyors

VESSEL'S NAME

Atchafalaya

Report

Ahr

No.

8027

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Cargo battens

A report of some alterations and repairs carried out at Aberdeen was before the Committee on the 2nd instant, when the vessel was allowed to remain as classed with record of survey, subject to the certificate of classification having the words written on it, "subject to the vessel being engaged exclusively in carrying coal, ore, or wood while without cargo battens."

A letter has now been received from the Aberdeen Surveyors stating they regret having omitted to state in their report that the vessel has been fitted with spar ceiling in the holds.

It is submitted the vessel should now be allowed to remain classed without special conditions.

as now } without
special
conditions



© 2019

Lloyd's Register
Foundation

ABNSZ-0047