

Is screw shaft now been drawn and examined?

yes

Is it

with oo

Is shaft now been changed?

1

ayed, awaiting  
particulars of new boiler  
from Gls. not yet to hand.  
R.H.

Lloyd's Register  
Foundation

ARV32-0044

Shafts,  
pumps & pumping arrangements  
The following repairs due to the