

S. "Syndiane" ex "Armeda"

Submitted the report on the
Chand Boiler of this vessel
and be returned to the
owners. ^{It} should be pointed
to them that it is considered
mention should be made
in report of the indentations
on shell of the boiler, described
in letter of May 28; they should
at same time state that these
indentations do not affect the
safety of the boiler in any

A.R.K
3.9.13

Ln. - 3/9/13



© 2019

Lloyd's Register
Foundation

ABN32-0157