

"British Queen"

Built 80-11m

Dec. 81 - At Lpool - due to stress of weather -
5 linths of planking slightly started
& strained - re-riveted. 20 keelsons
removed at heel of stern post.

Jan '86 - London - Butts at bilge amidships
observed to be rather wasted.

Feb. 89 London - Butts of bilge not in
very good condition, and require
to be dealt with within a year.



© 2021

Lloyd's Register
Foundation