

Myself

218

18

3898  
144

1 6 6 0 5 1/4 1/16

Continued





Sept 14

Siemens Steel Plates Contd

2 1/2	2 1/2	Plates 9. 4 x 1 1/4 x 1	3717	3718
			316 a	316 a
2	.	6 11 x . . .	3718	3718
			316 a	316 a
2	.	6 7 x . . .	3718	3718
			316 a	316 a
3	.	3. 5 x 2. 8 x 1/4	3718	3718
			316 a	316 a
1	.	2. 10 x 2. 3 x 1 1/2	3718	3718
			316 a	316 a
2	.	To Sketch x 3/4	3718	3718
			316 a	316 a
2	.	" x 1/2	3718	3718
			316 a	316 a
1	.	6. 6 x 14. 0 x 3/4	3718	3718
			316 a	316 a
1	.	To Sketch x 1/2	3718	3718
			316 a	316 a
1	.	" x 1/4	3718	3718
			316 a	316 a
1	.	" x .	3718	3718
			316 a	316 a

10468 Siemens Steel Plates

2 1/2	3	Steel 9. 6 x 14. 0 x 3/4	3771	3776	3777
			252 B	252 B	252 B
	6	6. 6 x 0. 5 3/4 x 1/4	3793	3731	3731
			316 a	253 B	253 B
	2	7. 7 x 2. 11 x 1/2	3720	3769	
			316 a	316 a	
	2	6. 11 x . . .	3763	3723	
			237 B	243 B	
	2	6. 7 x . . .	3723	3756	
			316 a	316 a	
	3	3. 5 x 2. 8 x 1/4	3759	3759	
			252 B	252 B	
	1	2. 10 x 2. 3 x 1 1/2	3774		
			252 B		
	2	To Sketch. x 3/4	3719	3724	
			324 a	324 a	
	2	" x 1/2	3775	3776	
			316 a	316 a	
	1	6. 6 x 14. 0 x 3/4	3762		
			257 B		
	1	To Sketch x 1/2	3730		
			316 a		
	1	" x 1/4	3741		
			252 a		
	1	" x .	3795		
			199 a		

2 1/2	3	Plates 9. 6 x 14. 0 x 3/4	3771	3772	3773
			252 B	252 B	252 B
	6	6. 6 x 0. 5 3/4 x 1/4	3771	3771	3771
			316 a	316 a	316 a