


(Received in London Office



Tests of 2 Steel *pl.* manufactured by The Steel Co Scotland of *Blackburn*
for Boiler No. 122 to be constructed by *J & J. Thomson* of *Glasgow*
for *workman black* *no 45*

Date first visit last visit No. of visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to _____ / samples as set forth below, and the temper and bending tests satisfactory

[illegible]

DA.
8/1/87

Fee £ : :

Expenses £ : :

£ : :

To be paid by

John Sanderford
Surveyor, Lloyd's Register,

Surveyor, Lloyd's Register.

Glasgow

4/1/84