

LLOYD'S REGISTER OF SHIPBUILDING
 RECEIVED
 23 APR. 88

TESTS OF BOILER STEEL.

Tests of 3 Steel Plates manufactured by Messrs David Colville & Son of Motherwell for Boiler No. 132 to be constructed by Messrs J. & J. Thomson of Glasgow for Messrs Workman Clark & Co. S. S. No. 58

Date first visit April 17th 1888 last visit April 20th 1888 No. of visits

The specified in the accompanying copy of Advice Notes were rolled from charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests to a shearing from each plate with satisfactory results.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brth.	Area.	Total.	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	Furnace Front	4552		3172	.63	1.43	.900	2668	29.6	21.5	

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by

© 2019

H. W. Done
 Surveyor, Lloyd's Register.
 Glasgow
 29-4-88

BESS-0260