

No. 8218

(Received at London Office)
 LLOYD'S REGISTER OF SHIPPING
 RECEIVED
 -4 AUG. 88

TESTS OF BOILER STEEL.

Tests of 1 Steel plate manufactured by *The Steel Co of Scotland of Glasgow*
 for Boiler No. *214* to be constructed by *Messrs. Harland & Wolff of Belfast*
 for *Shew Sp. No. 214 British Empire Bel. Report No. 3550*

Date first visit *24/7/88* last visit *2/8/88* No. of visits _____

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to 1 samples as set forth below, and the temper and bending tests *Satisfactory*

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brlth.	Area.	Total	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
	<i>Strap 3/8"</i>	<i>4.228</i>		<i>687</i>	<i>.99</i>	<i>1.38</i>	<i>1.366</i>	<i>38.25</i>	<i>28.0</i>	<i>25</i>	<i>m 8-8-88</i>

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by _____

J. J. Roberts
 Surveyor, Lloyd's Register.
Glasgow
2/8/88

RELS 0306