

Stl. Bk. "Hornth"

Bel. 1st Entry Rept. No. 4058

It is submitted that before this
case is put forward for the Committee's
consideration, the Society's Surveyors at Belfast
should be requested to state whether the
lower deck beams fitted in this vessel
are $10" \times \frac{11}{20}"$ as marked in their Report
or $11" \times \frac{10}{20}"$ as originally approved and
as required by the Rules in vessels over
39 feet beam in which no Quarter Pillars
are fitted.

G.B.

9.3.92

The Rept. is sent back herewith
as a reply for return of post should be
asked for.

Let to Bel. 9/3/92.

First Entry Report ref^d



© 2019

Lloyd's Register
Foundation