

## Steel Sailing Ship "Lauriston"

With reference to the Belfast Surveyors' letter of the 9<sup>th</sup> Jan., and their statement that one of the Builders would call here shortly in reference to the deficiency in the weight of the chain cable supplied to the "Lauriston", it is submitted the Surveyors should be requested to state whether it is still the intention of the Builders to call, or whether any steps have been taken to obtain an undertaking from the Builders to replace the chain cables with others of the required weight.

Ln to Belfast  
4/2/93

G.S.  
4.2.93



© 2019

Lloyd's Register  
Foundation

BEL61-0072