

Lloyds Register of British
and Foreign Shipping.

Belfast

23rd January 1894

LLOYDS' REGISTER
LONDON.

REC'D 24 JAN. 94

ANBR

The Secretary
London

Sir,

Regarding the delay in forwarding the First Entry reports on the S.S. "Ardanrose", to which your letter of yesterday refers, I beg to say that the vessel left here on Tuesday last for Ardrossan after a successful trial; & on Saturday she returned with the front end seams of the furnace flues leaking. These seams are now being partly riveted, & a longitudinal stay between the flues fitted in each boiler. The boilers are duplicate of those in the S.S. "Ardandhu" (Bel. rep 4261). The First Entry report upon the machinery is being retained until the work can be reported as satisfactorily finished.

I am Sir

Your obedient servant

A. L. Jones

Lloyd's Register
Foundation

BC62-0191

strength of joint
of furnace Top 5' 2" Bottom 6' 0" Length of furnace 6' 6" Thickness of shell crown plates 1/16 Radius of do. 211 No. of Stays to do. 9

urnace
80



© 2019
The Register
Foundation

Also for Mr. [unclear]
to write
J. H. [unclear]
24/1/94

24/1/94