

Received by Chief Surveyor 6/11/96

Received from Chief Surveyor _____

SEL'S NAME Sgt. S. S. Magician Report Bel No. 4668

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	✓	
Spar Sheerstrake . .	$\frac{2}{20}$	Proportions
Description of Framing:— <i>Semi-deep framing in conjunction with wide spaced hold beams.</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 A.1. "Steel" Spar Deck as recommended.

100 A.1. "Steel"
"Spar Deck"

1 Str (Stl) & Spar Str (Str) 3 to 13.

WB = Cell D.B a 118' u E & B 48' f 152' 8 7/27 F.P.T. 807 A.P.T. 607
F.K. Cem.

E. J. M.
C. A. J. 6/11/96

The Surveyor should be requested to state if the depth of the margin plate, as given on the Report viz 44" is correct



BEL-67-0002