

# Lloyd's Ship and Engineer Surveyor's Office.

E. Hougland,

Inspecteur for Lloyd's Register  
of British and Foreign Shipping.

BERGEN 16<sup>th</sup> December 1884

B. Weymouth Esq:

Secretary to Lloyd's Register of British and Foreign Shipping  
2 White Lion Court - Cornhill  
London

Sir! -

In reply to your honoured letter of 9<sup>th</sup>  
December regarding S.S. "Ladrelaudet" I beg to state  
that I have made a mistake in my report. -  
The intercostal keelson plate is  $8\frac{1}{16}$ " in the vessel  
and not  $5\frac{1}{16}$ " as erroneously stated. -

The bulk plate to the bulge keelson extends  
through Engine and Boiler space and three frame  
spaces into the tanks. -

I am, Sir!

Your most obedient Servant  
E. Hougland



© 2021

Lloyd's Register  
Foundation



23/12/84

R. W.

Case for the Chief

Subcommittee

of 13/12/84

BGN1105/202



© 2021

Lloyd's Register  
Foundation