

at Appledore by Messrs Cock & Sons.

cock & Sons
Appledore

Sent to Chief Surveyor 25-6-95

Received from Chief Surveyor

VESSEL'S NAME

Wood In Dione

Report Apl.

No. 2529

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st Entry.

It is submitted that before this case receives the consideration of the Committee the Report should be returned to the Surveyor and he should be requested to insert therein particulars of the tests of the 45 fms of $\frac{3}{16}$ " stream cable & state whether this cable is ~~open~~ short or stud link: also he should state whether he is correct in giving the test of the $\frac{7}{8}$ " stud link cable as $9\frac{1}{8}$ tons seeing that this is the test for $\frac{7}{8}$ " short link cable.

A prompt reply should be requested.

Tr. to appl.
25/6/95.

A.M.D.

C. N. J.
25-6-95



© 2019

Lloyd's Register
Foundation

BIN76-0033

BIN76-0035

Tenth
5
-
2
3
-
-
8
-
s.
H. P.
H. P.
d of S
of To
2.90
3.12
2.38
1.20
1.40
4.9