

The remarks of the Chief Surveyor are required to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs and to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.)

Sent to Chief Surveyor

VESSEL'S NAME

For the CHIEF SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

Received from Chief Surveyor

Report

Nature of Survey

When due

The 3rd S.S.No.3 is being held on this vessel at Appledore.

and the Surveyors now forward a sketch shewing the thicknesses of the plating as ascertained by drilling. As compensation for the deterioration which has taken place they recommend that a strake below the sheerstrake be doubled from the foremast to the mizen mast in addition to some repairs of a local character.

It is submitted the Surveyors recommendation merits the approval of the Committee.

Lt Apr 9/12/98



© 2019  
I.H.T.

8/12/98

BID77-0231

The Surveyor should be requested to  
The Register Book is now