

S/S "New Zealand"

ted the Appledore Surveyor should be that the plans forwarded by him having the proposed alterations to the iron steamer "aland" are receiving consideration.

Surveyor should point out to Messrs Cook & Sons "New Zealand" is an iron steamer and not a tanner as stated by them on the application submitted for approval.

Surveyor should also inform the owners or representative that this case cannot be dealt with a view to the re-instatement of the classification unless the engines & boilers are submitted for survey.

the vessel must undergo the 2<sup>nd</sup> S.S. No 3 re-instatement of classification, in addition additional strengthening, which may be found on account of lengthening. The surveyor arrange for the drillings to be made of the stuff as required for that survey.

is further submitted that if this for re-instatement of class is proceeded surveyor should be joined in the survey and the senior ship surveyor at Cardiff be Surveyor

L.S.  
26.8.07

26/8/07

J.D.



© 2019

Lloyd's Register  
Foundation

BID77-0495

BID77-0196