



Lloyd's Register of British & Foreign Shipping.

LLOYDS REGISTER,
LONDON.

REC'D 16 NOV 1907

ANSR

Appledore

Reference

Providence

I have charged to Messrs. Cook
& Sons on 2nd July 1-0-0

Special Survey 4-10-0

and do 1-10-0

£4-0-0 being the amount of

fees for the building of ship

I have charged 10/- for Brothie and
being called at midnight to test the Tachometer
as the ship was waiting to take ship away
and I had repeatedly told them the Tachometer
had tested before leaving here, I may say the
same thing applied to the S.S. New Zealand as
they did not test the Tachometer until the ship
was ready for sea and I had to go on
board in the middle of the night

Providence moulded depth is 9.6 But the depth for 1st of
floor for 1st of main deck is 7-10 1/2 and I have made an
error. The Shearwater as fitted is 7-0 for 6-0 I am in
bank 60 fathoms of 5 1/2 and 60 fathoms of 4 1/2. Your obedient servant
60 fathoms of 3 1/2 and 60 fathoms of 2 1/2. Fred. 10 fathoms of 1 1/2. C. W. Webb
The Secretary

Referred to the Chief Ship Surveyor

as
NOV 16 1967

Referred to Mr. Mayne.

As noted

C.H.P.



© 2019

Lloyd's Register
Foundation