

1st Foothooks 9 1/2 10
 2nd Ditto 8 1/2 9
 3rd Ditto 7 1/2 8
 Top Timbers 2 1/2 3

Garboard to Bilge .. 4
 Bilge Planks 4
 Bilge to Wales 8 1/2
 Wales 4

Bilge Planks
 Ceiling in Flat
 Ditto Bilge to, Clamp
 Hold Beam Clamps
 Beam Ditto 2 1/2
 'twixt Decks
 Beam Shelves ..
 Beam Ditto ..

Gloucester Sept 10th 1844

Mr. B. Syfang Esq
 London.

In reply to your est. favor
 of the 10th inst. we beg to say that the
 anchors & chains were contracted for
 on the 26th July last; we sincerely
 trust you can arrange for the passing
 of the certificates of test; it will be a
 serious loss to us if the vessel is
 detained.

Awaiting the favor of further

We remain Dear Sir
 Yours respectfully
 Miller & Co
 M.B. Jones

enails.
 Waterway ..
 Knees
 Shelf or Clamp
 Waterway ..
 Knees
 Shelf or Clamp
 Flat of Deck
 Inches ..
 Top-Timbers is

from thence do
 N. B. If not, state
 at that place.
 of Windlass is
 defects.
 eight Heads, Haw
 are free from
 Knees of
 Chain



Fastenings.—To Hold Beams Lodging Ropes in each Beam space and 13
 Hanging Ropes Ropes extending to lower part of Bilge.