

*Req wire*

Sent to Chief Surveyors

13 11 95

Received from Chief Surveyors

VESSEL'S NAME

*LSS Torbay*

Report

*BRW No. 000*

For the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee Report, 24/5/92.)

Nature of Survey

*ss No. 3*

When due

*2, 95*

The S.S. No. 3 became due 2, 95.

In reply to enquiry the Owners stated <sup>recently</sup> that the survey <sup>would probably</sup> ~~would~~ be held on the vessel's return in about a fortnight, but they ~~will~~ <sup>would</sup> advise definitely later ~~on~~.

The Owners now state that they have arranged to dock the vessel at Ardrossan, but as she is now bound for Kings Lynn, they propose sending her to Bilbao to load for Ardrossan, and trust this arrangement will be considered satisfactory.

A reply by wire is requested.

It is submitted the Owners be informed by wire that their proposal to send the vessel to Bilbao to load for Ardrossan is <sup>previous to holding the S.S. No. 3</sup> considered satisfactory.

In the meantime the class might be allowed to remain undisturbed.

*4/10/95* *J.D.L.* *2020* *95*



Lloyd's Register  
Foundation

BRW44-0091