

F.E.

Received by Chief Surveyor 6/5/96

Received from Chief Surveyor

VESSEL'S NAME H.S.S. "Clan Lindsay" Report Bm No. 719

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Items.	Additions (if any) required by Rules.	On account of:—
Main Sheerstrake . .	✓	✓
Spar Sheerstrake . .		
Description of Framing:— <u>Ordinary</u> . (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

+100 A.I. ("Steel") as recommended.

+100 A.I. ("Steel")


2 Dk (1 Hk, U. Trn. W.S.) & Web frames.

W.B. = Pell. D.B. a 82, u.E.B. 42, f 130, 535 t, F.P.T 97t, A.P.T. 38t.

B.K. 10" Perm.

6/5/96

Y.B. © 2020



Lloyd's Register Foundation

BRW44-0155

"	"	"	brdth. & thickness	18	8	18	8	"	Tie Plates
"	"	"						"	Deck Material and thickness