

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report.....18.....When handed in at Local Office.....18.....Port of Glasgow  
No. in Survey held at Glasgow Date, First Survey 19 May Last Survey 28 May 1898.  
Reg. Book. on the Wood, Iron or Steel Steam Trawler "Jaboo" Master B. Brett 10-28  
YEAR. MONTH.

TONNAGE:— Built at Liverpool By whom James Watson & Co. When 1898 5  
GROSS Owners Liverpool Steam Fishing Co. Limited Port belonging to Liverpool  
UNDER DK. Owners' Address  
NET (if not already recorded in Appendix to Register Book.)  
Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage Boasting

WB=CellDBorDBa feet; uE&B feet; f feet; }  
total capacity tons. FPT tons; APT tons; MT feet tons. }  
N.B.—All alterations in the existing records should be underlined.  
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. Port  
(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)  
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).  
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion on Secretary's letter M 19/5/98

The Engine & Boiler casings have been riveted up and efficiently enclosed; Land pumps tested, chain cables and anchors examined and compared with certificates  
This vessel being for trawling purposes only, the testing of deck was dispensed with see Sec. letter M. 1/12/96  
1<sup>st</sup> Boiler S. 2. 0. 0 Stokers 12 of cut. 32990. Sunderland 1/3/98. H. J. Holford. Suppt: 5. 0. 0. 0  
2<sup>nd</sup> Boiler S. 0. 0. 0 Stokers 12 of cut. 32989. Sunderland 1/3/98. H. J. Holford. Suppt: 5. 0. 0. 0  
Spare - 4 - S. 0. 0. 0 Stokers 12 of cut. 32991. Sunderland 1/3/98. H. J. Holford. Suppt: 5. 0. 0. 0  
Makers of anchors. G. H. Reed. Cast Steel Heads. Steel 6" of Scotland }  
Cast by W. R. Knight 14/1/98 }  
75 ft. 10/16 steel link weight 34. 3. 24. Test cert. 27995 Hetherton 3/2/98. H. J. Holford. Suppt: 5. 0. 0. 0

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed ... ..								
Faired or Repaired ...								

PRESENT CONDITION OF THE	Timbers of Frame at the openings	Rudder	Hatches
Decks	Ditto ditto at other places	Windlass & Capstan	Boats
Waterways	Keelsons	Have Pumps now been examined and found efficient?	Masts, Yards, &c.
Coamings	Stringers, Clamps & Shelves	Have Sluice Valves now been examined and found efficient?	Condition, how ascertained (State if wedges removed)
Up'r Dk. Beams & Fastenings	Salting (State if examined.)	Have Watertight Doors now been examined and found efficient?	Sails
Low'r Dk. Beams & Fastenings	Ceiling	Dblg. Plates under Sounding Pipes	Equipment letter
Plating	Cement or Asphalt (State which.)	Engine Room Skylights	Anchors, No. of
Planking	Tanks (State if now tested.)	Coal Bunker, Open'gs, Lids, &c.	Cables (State if now ranged)
Rivets or Treennails	Caulking of Bot'm, D'k, & Wat'rwys.	Scuppers	" length size (on board)
Breasthooks & Stemson	Copper, or Y.M. (State if on felt.)	Cargo & Main H'tch'wys	" Rule length size (per Table 22)
Transoms, Pointers, & Crutches	When put on, Month Year		Hawsers & Warps

General Observations, Opinion as to Class, Recommendation, &c.:—  
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,97," or "to remain as classed and to have record of survey, 1,97, and the notations of ss No. 1-97 and ptND97, &c."  
The above was completed survey of this vessel.

Office Fee (if chargeable) per Scale II., Sec. 27 .....£ : : Fees applied for, :  
Survey Fee (per Section 25) .....£ : : 18  
Special Damage or Repair Fee (if any) .....£ : : Received by me, :  
(per Sec. 28.)  
Travelling Expenses (if chargeable) .....£ : : 18  
Second Surveyor's Fee (if any) .....£ : :  
Committee's Minute  
Character assigned  
TUES. 14 JUN 1898  
See 1<sup>st</sup> - Embury Report

