


It is submitted Mr. Champness, the Principal Surveyor at Newcastle, should be requested to call upon Messrs Sharp & Co. of Lombard Street, Newcastle on Tyne, the owners of the S.S. "Dunmail", and inform them that it is understood to be their intention to place the vessel under survey in order to effect repairs which have been found necessary in the deck plating and shaft tunnel. Mr. Champness should ascertain and report to this office as promptly as possible where and when these repairs are to be carried out in order that the necessary instructions may be given to the surveyors. The repairs should be effected without any delay.

H. J. B. 25/2/08

J. M. 25.2.08

Note: When reply is received - that vessel became ^{no} 2 - S.S. No 3 in May last



© 2021

Lloyd's Register
Foundation