

Iron Screw Steamer "William Hayes"
late Guadiana) built at Renfrew
in 1866 - 1-mo and classed A.1. class
omitted.

It is submitted Mr Lochrane
should be requested to state whether
the scantlings as shown on the
report are as actually ascertained
by him by drilling the plating & or as
given originally in the vessel
the report should be returned
for completion where crossed in pencil.

It is observed that in some
respects the scantlings given on the report
are in excess of those shown on the
original first entry report.

Mr Lochrane should also state in detail the
extent of the survey held by him at the present
time for the information of the Committee.

Lo. 11. 11. 87.

J. H.
11/11/87

Mr. L. G.
W. L. L.

© 2021
Lloyd's Register
Foundation