

How are the mums worked

For Mr. Gillespie

B.M.

W. Althaus

Report No. 3344

For the Chief
Engineer Seamen's opinion
asked for Manufacture
of Machinery, and
of Boilers

Machinery 1886
Boilers 1886

7.9.87
J. S. 87
6 July

LLOYD'S REGISTER,
LONDON.
REC'D - 7 JUL. 87
AN85



© 2019

Lloyd's Register
Foundation

diameter of Superheater or Steam chest 2.6 length 6ft thickness of plates $\frac{1}{16}$ description of longitudinal joint *double lap* diam. of rivet holes $\frac{15}{16}$
pitch of rivets 2.5 working pressure of shell by rules $\frac{1}{4}$ diameter of flue thickness of plates If stiffened with rings