

S. S. "Laughton" late SS "Nord Brandenburg"

This case has already occupied the attention of the Committee when Mr Loos was requested to offer any remarks he may have to make on the subject of the repairs to the tank top under the Boilers.

Mr Loos' reply has been now received, he is sorry that the condition of the tank top under the boilers was not observed by him, and there is no doubt that in future Mr Loos will be particularly careful in examining the condition of this part.

J.D.H.
15/1/92

G.B.



© 2019

Lloyd's Register
Foundation

LRF-PUN-CFF84-0174