

4.)

Chief Surveyors 28305 Received from Chief Surveyors _____
 VESSEL'S NAME S.S. Eastry Report Off No. 20039
 For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

No. 3 SURVEY PARTLY HELD.

due 3 04 When proposed to be completed _____

on of Survey held, &c. _____

The S.S.No.3, due 3,04, was partly held at Cardiff in August last.

To complete the survey the holds above close ceiling require to be examined, the plating drilled if considered necessary, bunkers cleared and examined, tank in engine space scaled internally and the floors and intercostals in same examined, and the pumps, sluices and WT doors examined.

The Manchester Surveyors now forward a letter from the Owners in reply to enquiry stating that the vessel is at present in Eastern waters and they are trying to fix her home when they will complete the survey.

The year of grace expires at the end of the present month.

The owners proposal is submitted for the consideration of the Committee.

Handwritten: F.L.M.C. 8.04 assigned.

Handwritten: to be put out in a this time.

Handwritten: F.L.M.C. 31.3.05

Handwritten: F.M.S. 29.3.05
Handwritten: J.L.S. 29.3.05



© 2010
 29/3/05

Lloyd's Register Foundation

LRF-PUN-CFF85-0083