

Received by Chief Surveyor 6.12.97

Received from Chief Surveyor

EL'S NAME *St. S.S. "Araklis"*

Report *Gru* No. *1062*

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

*First entry*

It is submitted that before this case receives the consideration of the Committee, the report should be returned to the Surveyor, and he should be informed that unless the first and second bower anchors are tested at a Machine recognised by the Committee, or at a Government Machine, or at a Machine under the control of a Municipal Body, or a similar responsible body, as set forth in the Rules for Steel Ships, Sec39. par.81, the vessel cannot be recommended as eligible for the figure 1 for equipment, and under these circumstances he should ascertain what steps the Builders will take in the matter.

*Mr. W. P. G. G. G.*  
*7/12/97.*

*C. K. J.*  
*6/12/97*



© 2021

Lloyd's Register  
Foundation