

REPORT of SURVEY for REPAIRS.

No. 10 Survey held at London Date, first Survey 4 Dec^r Last Survey 9 Dec^r 1842
 on the Ship "T. Light Brigade" Master L. A. Davies
 Tonnage 1214 built at Bathurst U.S. When built 1853
 By whom built William Stoo Owners William Stoo
 Port belonging to London Destined Voyage Greenland
 If Surveyed Afloat in Dry Dock Repent's Dry Dock & E. J. Dock.

Last Survey, No. 10 Port London Classed as requested

REPAIRS, &c.

Vessel examined for the purpose of
 classing "1 F. 1" as requested -
 Lighted Bottom, and tried caulking;
 but further Survey declined for the
 present -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Roatings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Deerstrakes	Clamps and Shelves	Anchor No. of
Oppsides	Ceiling	Cables
Stales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		
Hatches		

General Observations and Opinion,

Requirements of Rule } — Murray. J. Syrell
 not complied with — Samuel Wilson

The Amount of Entry Fee... £ 10 is received by me,

Special... 10

Certificate (if required) : :

Committee's Minute

18

Character assigned



© 2019

Lloyd's Register
 Foundation

CRK93-0224