

Steel Bk. "SACHSEN".

It is submitted that Mr. Attridge should inform the Owners that the anchors and chains must be tested as required by the Rules to entitle the vessel to the figure 1.

It should be pointed out that the certificates for the ^{two} anchors signed E. Evensen cannot be recognised by the Society, as *they were not tested at a proving house recognised by the Committee*.

Dr. to Ques. 19/5/99

2 plans + 2 test Cert returned
P. b. to Off.

J. H. C. B.

18.5.99

B. M.

H.

W. H. H.



© 2019

Lloyd's Register
Foundation