

989

This vessel is evidently not of that superior description which is contemplated for the 12A grade - Grain cut futtocks - floor beam and futtock heels not in close contact - the shortness of the stiff between the scamps of the keel and keelson - inferiority of Sturges Treasails fastening - a serious defect in a waterside already of exceedingly small scantling - Breest hooks not of the best description - the method of shipping the Butts of the plank, if the Butts be studded as the sketch would lead us to infer - and in fact all the objections recapitulated in the report of the local Surveyor, are such as should not be made to any 12A ship. Though there is not one which can be urged out to contradict the opinion made by Messrs Follett respecting deviation from the rules - all the objections being on matters which the rules by inference require to be free from objections -


 Al.  
 Feb. 19<sup>th</sup> 1848

 Lloyd's Register  
 Foundation