

Surveyors

29.7.10

Received from Chief Surveyors

NAME

Lt. British Queen

Rpt.

Dub

No.

2937

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

3rd No. 2

SURVEY PARTLY HELD.

9.09

When proposed to be completed

Survey held, &c.

It is submitted the Owners be asked to state what arrangements they propose to make for the repair or renewal of the mudders as recommended by the Dublin Surveyor in order to complete the works.

[Signature]

R/B
29/7/10

to Owners



© 2019

Lloyd's Register Foundation

DUB99-0066