

Received by Chief Ship Surveyor 16-3-14

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S. S. Bray Head Rpt. Dub No. 3351**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Damage & part 2<sup>nd</sup> S. S. No 2.

It is submitted that before this case receives consideration, the Surveyor should be requested to state the number of plates of which the butts have been welded up; and also by what process of welding they were done with. this was done

ln 17/3/14

M. G. S.  
17-3-14



© 2019

Lloyd's Register  
Foundation

DUBA-0187

foreman

5.