

Schooner "Olwen"

Rudder.

It is submitted the Surveyor be informed that as it appears from his letter the reparation to the rudder was made some years ago and as the rudder has proved satisfactory during that time no action need be taken in the matter.

No. 1.7.14
And

C.F.
3.7.14



© 2014

Lloyd's Register
Foundation

DVB99-0257