

TELEGRAPHIC ADDRESS: "CALEDON, DUNDEE"

*Lilybank Engine Works.*

ON & CO LIMITED.  
UILDERS  
INEERS.

(ALSO AT TAY ENGINE WORKS & CALEDON SHIPBUILDING YARDS.)

*Dundee* 18th. September 1891

Keydell Esq:

Lloyds Surveyor,

D U N D E E.

Sir,

S.S. "PEREGRINE"

Since you mentioned to me a few days  
the deficiency in the collective weight  
the Anchors for the above Steamer, I have  
investigating the matter and I find that  
error has been made in our Shipyard  
ing Office and has arisen in changing  
second Bower from a Porters Anchor to a  
kless one. I am very sorry that this  
ake should have occurred, but as the  
ciency in weight is not great we trust

that your Committee will overlook it in this  
case and we will take special care that such a  
thing shall not occur in the future.

Yours truly,

*A. W. Anderson*  
*Secy*



© 2019

Lloyd's Register  
Foundation

DUN118-0139

*Landon*