

Runde.

Bought of the Stockton Malleable Iron Co. Limited.
Siemens Martin Steel.

Date	Plate No	Charge No	N ^o of Plates	Length	Breadth	Thickness	Mark	Ship	Tons, cwt, qrs, lbs.
1891									
Dec 22 nd	9410	725	1	13-5 $\frac{1}{2}$	44	10/20	7/11	(111)	
			1	13-7 $\frac{1}{2}$	32 $\frac{1}{2}$		C3		
	9431	726	1	13-6	43		-5		
	9433		1	19-3	43 38		B1		
			1	13-6	40 $\frac{1}{2}$ 44 $\frac{1}{2}$		C14		
	9438	724	1	15-9	38 32 $\frac{1}{2}$	11/20	-2		
	9837	730	1	12-3	29 28	10/20	62		
	9838		1	-	-		-		
	9839		1	14-2	28 19		-14		
	9841	H400	1	13-5 $\frac{1}{2}$	51 49 $\frac{1}{2}$		D16		
	9842		1	-	52 40 $\frac{1}{2}$		C16		
			1	-	52 $\frac{1}{2}$ 51		B5		
	9845	728	1	5-0	21 10	1/2	S8		
	9850	H2014	2	10-6	56 38	12/20	C1		
	9851	H405	1	13-5 $\frac{1}{2}$	52 40 $\frac{1}{2}$	10/20	-16		
	9852	H422	14	1-4 $\frac{1}{4}$	36	14/20	-7/14		
			2	-	54 $\frac{1}{2}$		-15		
			1	-	40		-6		
	9854		2	9-6	50	5/8	S1		
	9858	A2010	1	14-2	28 19	10/20	S14		
	9864	J438	2	13-9	43 39	9/20	D5		
	9865	733	1	15-6	50 43 $\frac{1}{2}$	12/20	AS1		
	9866	731	2	13-5 $\frac{1}{2}$	39	11/20	-4/5		
			1	13-7	41 33		AS19		
	9867	723	1	14-9	56 $\frac{1}{2}$ 53	7/16	M19		
	9869	731	1	13-5 $\frac{1}{2}$	39	11/20	AS16		
			1	13-9	40 30		AS14		
			1	13-5 $\frac{1}{2}$	39		-16		
	9873	733	1	14-9	56 $\frac{1}{2}$ 53	7/16	M19		
			1	11-7	51	9/16	B17		

Received
25/12/91

Received
25/12/91

48

Surveyor to Lloyd's Register

1/4 1/2 1/2 2/1

DWV 120-052