

Stockton-on-Tees.

Messrs W. B. Thompson &amp; Co.

London

Bought of the Stockton Malleable Iron Co. Limited.  
Siemens Martin Steel.

| Date<br>1893 | Plate<br>No. | Charge<br>No. | No. of<br>Plates | Length   | Breadth   | Thickness | Mark   | Ship  | Tons. | cwt. | qrs. | lbs. |
|--------------|--------------|---------------|------------------|----------|-----------|-----------|--------|-------|-------|------|------|------|
| July 24      | 723          | 3034          | 1                | 16.6     | 49        | 6/30      | MLDB1  | (122) |       |      |      |      |
|              |              |               | 1                | 4.6      | 30        |           | LDP5   |       |       |      |      |      |
|              | 724          |               | 1                | 18.4     | 49        |           | MLDB10 |       |       |      |      |      |
|              | 725          |               | 1                | 11.11    | 46 45 1/2 |           | MLDB6  |       |       |      |      |      |
|              | 726          |               | 1                | 11.6 1/2 | 44        |           | BOP4   |       |       |      |      |      |
|              |              |               | 1                | 10.10    | 40 11 1/2 |           | MLDC1  |       |       |      |      |      |
|              | 728          |               | 1                | 13.8 1/2 | 48 1/2    |           |        | 3     |       |      |      |      |
|              |              |               | 1                | 11.11    | 46 45 1/2 |           | MLDB6  |       |       |      |      |      |
|              | 729          |               | 1                | 12.9     | 48 1/2    |           | MLA8   |       |       |      |      |      |
|              |              |               | 1                | 11.11    | 46 44 1/2 |           | MLDB9  |       |       |      |      |      |
|              | 730          |               | 1                | 14.10    | 49 1/2    |           | MLDC16 |       |       |      |      |      |
|              | 734          |               | 1                | 17.6 1/2 | 49        |           | MLB2   |       |       |      |      |      |
|              |              |               | 2                | 3.3      | 12        |           | PDP8   |       |       |      |      |      |
|              | 735          |               | 1                | 13.8 1/2 | 48 1/2    |           | MLDC3  |       |       |      |      |      |
|              |              |               | 1                | 11.11    |           |           |        | 11    |       |      |      |      |
|              | 737          |               | 1                | 14.6 1/2 | 49        |           | MLDB5  |       |       |      |      |      |
|              |              |               | 1                | 10.10    | 40 11 1/2 |           | MLDC1  |       |       |      |      |      |
|              | 739          |               | 1                | 12.8 1/2 | 48 1/2    |           | MLA11  |       |       |      |      |      |
|              |              |               | 1                | 13.8     |           |           |        | 3     |       |      |      |      |
|              | 742          |               | 1                | 15. 1/2  |           |           | MLDC2  |       |       |      |      |      |
|              |              |               | 2                | 11.3     | 0         |           | PDP5   |       | 5     | 9    | 3    | 14   |
|              |              |               | 23               |          |           |           |        |       | 5     | 9    | 3    | 14   |

Surveyor to Lloyd's Register.



© 1893

Lloyd's Register  
Foundation

DAN 112-0215