

Report No 6499.Port of Dundee29th April 18999

REPORT ON MASTS, SPARS, AND RIGGING.

Gentlemen,

Having, in accordance with your instructions, examined the Masts, Spars, and Rigging, and Iron Work of same, of the

Iron 4 Mast Ship Liverpool.

I have to report that I found the fore topmast-bent; fore topgallant-gard defective: wedges of fore royal yard started: fore topgallant-mast preventer broken: mizzen topmast and mizzen topgallant-mast broken: fore trestle-trus started and a number of stays blocks be missing the vessel having been partly dismasted.

Fee £ - : 10/-

To the Surveyors,

Lloyd's Register of British & Foreign Shipping,

Dundee

Hector Bennet Sparrow



© 2021

Lloyd's Register
Foundation

DUN128-0053