

Port of Dundee

14th July 1900

REPORT ON MASTS, SPARS, AND RIGGING.

Gentlemen

Having, in accordance with your instructions, examined the Masts, Spars, and Rigging, and Iron Work of same, of the

Steel 4 Mast. Bk. "Lindia"

I have to report that I found the Mizzen topgallant mast and the fore upper topgallant yard defective; all other parts were in good condition.

Fee £ 0 : 10 : 0

To the Surveyors,

Lloyd's Register of British & Foreign Shipping,

Dundee.

Victor Bennett
Surveyor



© 2020

Lloyd's Register
Foundation

DUN130-0129.1