

No. of Houses on Deck  
No. of excess of Hatchways

Depth from upper part of keel to top of main Deck Beam  
Girth of Half Midship Frame (as per Rule)

By whom built

GEN 1140086  
F.E.

Received by Chief Surveyor 17-4-99

Received from Chief Surveyor

EL'S NAME *M. G. "Venus"* Report *Gen* No. *1780*

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .		
Spar Sheerstrake . .	<i>4/40</i>	<i>Proportions</i>
Description of Framing:— <i>ordinary</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *100A1 "Spardeck" ("Steel")* as recommended.

*100A1 ("Steel") "Spardeck"*

*12h (Stl) & Spardeck (Stl) & 3h B*

WB = Cell 0B a 88' u E & B 42' f 156' 734' MT 28' 740' APT 55k  
FK 7BH Cnm LA & CP

28 APR 1899



© 2020

Lloyd's Register  
Foundation