

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 3054** Survey held at Glasgow Date Decr 8<sup>th</sup> 1869  
 on the BK "Annie Braginton" Master John Drysdale  
 Tonnage 413 built at Shields When built 1860  
 By whom built \_\_\_\_\_ Owners N. D. Turcan  
 Port belonging to Glencardine Destined Voyage Penang  
 If Surveyed Afloat or in Dry Dock Kingston Dock

Last Survey, No. 28264 Port London Classed 13 A. 1.

## REPAIRS

now done,

The Yellow Metal sheathing stripped off the bottom - caulked from keel to top of irons and the bottom re-sheathed with Yellow Metal upon Felt -

Surveyed for Half-time in March 1867

## Present Condition of the

Decks	} good	Treenails	} good	Windlass and Capstan	} good	
Waterways		Breasthooks and Stemson		Pumps		and
Comings		Transoms, Pointers, and Crutches		Boats		efficient
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.		from the deck
Lower Deck Beams & Fastenings	} where	Ditto Ditto at other places	} seen	Condition, how ascertained	} good	
Planksheers		Keelsons		Sails		and
Sheerstrakes		Clamps and Shelves		Anchors No. of 3 B/S 2K		and
Topsides		Ceiling		Cables		Sufficient
Wales	} seen	Rudder	} lumbered	Hawsers and Warps	} sufficient	
Plank (Bottom) and Counter		Copper F&YM When put on now		Standing & Running Rigging		u

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where seen

She is now where seen in good and efficient condition, fit in my opinion to remain as classed 13 A. 1.

The Amount of Fee.....£ : : : is received by me,

Special..... / : / : :

Det Mre

Certificate (if required) : : : :

Committee's Minute 14<sup>th</sup> December 1869

Character assigned 13 A. 1

record M. W. S.



© 2019

Lloyd's Register Foundation

GLS 144-270