

3120

# REPORT of SURVEY for REPAIRS.

No. in 7. Book. **No. 3120** Survey held at Glasgow Date 21<sup>st</sup> March 1870  
on the Comp. Ship 'Nathan Castle' Master Marshall  
Tonnage 690 built at Glasgow When built 1869  
By whom built Stephen Owners T. Skinner  
Port belonging to Glasgow Destined Voyage Clas Singapore  
If Surveyed Afloat or in Dry Dock Nathan Stephen's Shipway

Last Survey, No. 2974 Port Glasgow Classed 17A1  
REPAIRS 6.69

The metal sheathing having proved bad, has now been stripped and renewed.  
The caulking tested and found good.

Present Condition of the			
Decks	<u>Good</u>	Freecoils	<u>Good</u>
Waterways		Breasthooks and Stemson	
Comings		Transoms, Pointers, and Crutches	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings	
Lower Deck Beams & Fastenings		Ditto Ditto at other places	
Planksheers	<u>Where</u>	Keelsons	<u>Where</u>
Sheerstrakes		Clamps and Shelves	
Upsides		Ceiling	
Vales		Rudder	<u>Seen</u>
Plank (Bottom) and Counter	<u>Seen</u>	Copper	<u>When put on 3.70</u>
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.	
		<u>Good where tested</u>	

This ship is now in good and efficient condition, eligible to remain as classed.

The Amount of Fee.....£ : : : is received by me,  
Special..... : : :  
Certificate (if required) : : :  
*McM*

Committee's Minute 1<sup>st</sup> April 1870

Character assigned 17A1  
*revised G.M.M.*