

Report of Survey for Repairs of Engines and Boilers.

No. 4405

No. in Reg. Book. 397

Survey held at Dumbarton

Date, first Survey Feb 16th Last Survey March 12th 1878

on the "Black Diamond"

Owners Canshalland Coal Coy. Port belonging to Liver

Tons 134

Years assigned. 23

Character in Register Book. A.1

Classed 3.46

Diameter of Cylinder 30"

Length of Stroke 22"

Pressure of Steam 18 lbs

Nominal Horse Power 45

Engines made at Glasgow

By whom made G. S. Coate

When made 1864

Particulars of Repairs and Examination A new Crank Shaft has now been fitted, and Engines overhauled, Sea Cocks examined and ground up.

The above repairs have been satisfactorily completed by Messrs Henry & Coy. Dumbarton

The Amount of Fee ... £ ... : : received by me, }
Certificate (if required) ... £ ... : : 187 }
(Travelling Expenses, if any, £ ...)

Committee's Minute

18

James Morrison
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.