

# ANNUAL SURVEYS.

5555

No. 5555 Survey held at Glasgow Date, first Survey 16 Nov. Last Survey 28 Nov. 18 81

No. in on the Iron S.S. "Amara poora" Master J. Stuart  
 Reg. Book. 681 Net 1619 Built at Greenock When built 1874 Year. 7 Month.  
 Tonnage Gross 2464 Under Dk. 2427 By whom built Scott & Co. Owners British & Burmese Steam Navigation Co.  
 Port belonging to Glasgow Destined Voyage Rangoon  
 If Surveyed Afloat or in Dry Dock Henderson's dry dock and afloat  
 (State Name of Dock.)

Last Survey, No. 5479 Port of Glasgow? Classed 100 A. 1.  
 Present Condition of the Decks good Keels good SS. No. 1-78. 11.80.

Waterways good Breasthooks good Windlass and Capstan good  
 Comings good Transoms, Routers, and Scutches good Pumps good  
 Upper Deck Beams & Fastenings good ~~Frames of the~~ Frame at the Openings good Boats good  
 Lower Deck Beams & Fastenings good ~~Ditto~~ at other places good Masts, Yards, &c. good  
 Planksheers good Keelsons good Condition, how ascertained from deck  
 Sheerstrakes good ~~Clamps and Stays~~ Ceiling good Sails good  
 Topsides Plating Rudder good Anchors, No. of 3 B. 1 S. 2 K.  
 Wales good Copper or Y.M. good When put on good Cables said to be complete  
 Plank (Bottom) and Counter good Caulking of Bottom, Deck, & Waterways good Hawser and Warps good and  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 (If a Steam Ship, state if a Report is also sent on the Machinery.....)  
 General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated; the plating of the rudder renewed; ceiling repaired for the voyage, the owners having expressed their intention to renew the greater part of the ceiling on the return of the vessel to this port.  
This vessel is now in good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute Friday, December, 2nd. 1881. J. Stanbury.  
 Character assigned 100 A. 1. Surveyor to Lloyd's Register of British and Foreign Shipping.  
B.S. 7, 81 subject to Certificate (if required, to be sent as per margin) Paid 18

No. 5555 Survey held at Glasgow Date, first Survey 22 Nov. Last Survey 26 Nov. 18 81

No. in on the Iron S.S. Colina Master D. Maxwell  
 Reg. Book. 1029 Net 1297 Built at Glasgow When built 1872 Year. 10 Month.  
 Tonnage Gross 2001 Under Dk. 1302 By whom built Burley & Co. Owners Donaldson Bros.  
 Port belonging to Glasgow Destined Voyage Buenos Ayres  
 If Surveyed Afloat or in Dry Dock Govan dry dock & afloat  
 (State Name of Dock.)

Last Survey, No. 5281 Port of Glasgow Classed 100 A. 1.  
 Present Condition of the Decks good Keels good SS. No. 2-79. 1.81

Waterways good Breasthooks good Windlass and Capstan good  
 Comings good Transoms, Routers, and Scutches good Pumps good  
 Upper Deck Beams & Fastenings good ~~Frames of the~~ Frame at the Openings good Boats 4 No.  
 Lower Deck Beams & Fastenings good ~~Ditto~~ at other places good Masts, Yards, &c. good  
 Planksheers good Keelsons good Condition, how ascertained from deck  
 Sheerstrakes good ~~Clamps and Stays~~ Ceiling good Sails good  
 Topsides Plating Rudder good Anchors, No. of 3 B. 1 S. 2 K.  
 Wales good Copper or Y.M. good When put on good Cables said to be complete  
 Plank (Bottom) and Counter good Caulking of Bottom, Deck, & Waterways good Hawser and Warps good and  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 (If a Steam Ship, state if a Report is also sent on the Machinery.....)  
 General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated; the rudder lifted and the pintles bushed, and the defective rivets in the rudder renewed.  
Part cargo in the hold at time of survey.  
This vessel is now in good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute Friday, December, 2nd. 1881. J. Stanbury.  
 Character assigned 100 A. 1. Surveyor to Lloyd's Register of British and Foreign Shipping.  
B.S. 11, 81 subject to Certificate (if required, to be sent as per margin) Paid 18  
Dr to owners 8/12/81

Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.

9410-941575