

# Report of Survey for Repairs of Engines and Boilers.

No. 5555

(Received at London Office, 1/12/87)

No. in Reg. Book. 681 Survey held at Glasgow Date, first Survey 16<sup>th</sup> Nov Last Survey 24<sup>th</sup> Nov 1881  
on the Machinery of the Screw Steam "Amarapura" (Number of Visits 2)  
Tonnage, Gross 2464 Built at Greenock When built 1874  
Ditto, Net 1619 Owners British & Burmese S. N. Co. Ltd. Port belonging to Glasgow  
Diameter of Cylinder 45" x 78" Engines made by Greenock Foundry Co. When made 1874  
Length of Stroke 45 Boilers made by " " " When made 1874  
Pressure of Steam 65 lbs If Surveyed Afloat or in Dry Dock Hindenoni Dry Dock, Classed 100 A1  
Registered Horse Power 300 (State name of Dock.)  
Last Survey No. Port 13 & M. S. 9-79. 13 & S. 7-81.

Particulars of Repairs and Examination to complete 13 & M. S. see Glasgow Report  
(State cause of Repairs.)

N<sup>o</sup> 5444

Examined propeller & stern tube fastenings, in good order.  
Examined sea cocks & other connections, all in good order.  
Examined fitting of new low pressure slide valve, satisfactory.  
Examined fitting of new H. P. Eccentric, satisfactory.  
Some screw stays have been runned & a patch put on fore & aft furnace  
of port fore boiler.  
The old donkey boiler has been removed and the one ex "Tenasserim"  
which has been repaired & tested to 80 lbs per sq inch hydraulic pressure,  
put in its place & loaded to 40 lbs on sq inch working pressure.

General Observations, Opinion, and Recommendation:— The above examinations & repairs  
having been carried out satisfactorily the machinery is now in good order  
and safe working condition & eligible to be noted in the Register Book  
13 & M. S. 7-81 for twelve months, the boiler being old.

Entry or Registering Fee... £ : : :  
(per Section 27.)  
Survey Fee (per Section 28) ... £ : : : received by me,  
Certificate (if required) ... £ : : : 188  
to be sent as per margin.

(Travelling Expenses, if any, £ )

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute 188

Assigned

B & M S. J. P. Subject

Lloyd's Register  
Foundation

GLS146-0177



5555 GLS

His submitted that this results

uneligible to have the  
notifications Billed 7.8  
Recorded; subject to the bill  
very, however, no further

M. 1/12/8



© 2019

Lloyd's Register  
Foundation