

# Report of Survey for Repairs of Engines and Boilers.

(Received at London Office, 30th MAY, 82.)

No. 5418

No. in Reg. Book. 209 Survey held at Glasgow Date, first Survey May 23 Last Survey May 23 1882

on the Machinery of the Iron S.S. "Behera"

(Number of Visits 1)

Tonnage, Gross 1384

Built at Newcastle

When built 1864

Ditto, Net 1032

Owners H. Gilburn

Port belonging to Glasgow

Diameter of Cylinders 30" & 54"

Engines made by Comp by M. Paul & Co

When made 1879

Length of Stroke 36"

Boilers made by M. Paul & Co

When made 1879

Pressure of Steam 40 lb.

If Surveyed Afloat or in Dry Dock Govan Dry Dock.

Classed A1

Registered Horse Power 127

Last Survey No. S.S. No. 3 - 79

Port Glasgow

Lloyds M.C. 4.79

## Particulars of Repairs and Examination

(State cause of Repairs.)

This vessel being in dry dock, the propellor and propellor fastenings have been examined and found in good order.  
The sea connections were examined and are in good order.  
The engines and boilers were not opened up for survey.

General Observations, Opinion, and Recommendation:— As far as seen this vessel is in good and efficient condition, and eligible in my opinion to remain as noted in the Register Book, viz — Lloyds' M.C. 4.79.

Entry or Registering Fee... £ 0 : 0 : 0

Survey Fee (per Section 28) ... £ : : received by me, }

Certificate (if required) ... £ : : 188 }

(Travelling Expenses, if any, £ )

Committee's Minute

188

Assigned

George Rendall.

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Glasgow.

Lloyd's Register Foundation

GLS146-0408



5718-825  
It is submitted that no record  
is eligible to run with no record

30/5/80



© 201  
Lloyd's Register  
Foundation