

Report of Survey for Repairs, &c., of Engines & Boilers.

No. 6608

(Received at London Office, THURSDAY 14 AUGUST 1884)

No. in Reg. Book. 849 Survey held at *Glasgow* Date, first Survey *2^d Aug.* Last Survey *7th Aug* 1884
on the Machinery of the *S. S. Clan Macintosh.* (Number of Visits *3.*)

Tonnage, Gross *3985.* Built at *Greenock* When built *1883.*
Ditto, Net *2636.* Owners *Cayzer Irvine & Co.* Port belonging to *Glasgow.*
Diameter of Cylinders *48" & 86"* Engines made by *Scott & Co.* When made *1883.*
Length of Stroke *60"* Boilers made by *do.* When made *1883.*
Pressure of Steam *85 lbs.* If Surveyed Afloat or in Dry Dock *Glasgow Dry Dock and afloat.* Character in Register Book.
Registered Horse Power *600.* (State name of Dock.) Classed *100A1*
Last Survey No. Port *+ L.M.C. 8.83.*

Particulars of Repairs and Examination *Annual Survey.*
(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Cylinders, Condenser & pumps examined.
Main bearings, crank pins and tunnel shafting examined.
Brass studs fitted on Stern Gland in place of iron.
All sea cocks examined and overhauled.
Stern tube, propeller and fastenings examined.
Main and Donkey boilers examined and all safety valves overhauled.

General Observations, Opinion, and Recommendation:— *The above mentioned*
(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)
Vessel's Machinery is now in my opinion in good working condition and eligible to be noted in the Register Book: + L.M.C. 8.84.

Survey Fee (per Section 28) £ *2: 2: 0*
Special Damage Fee (per Section 28) £ - - -
*Certificate (if required) £ - - -
Travelling Expenses (if chargeable) £ - - -

received by me, *12/8/1884*

John Sanderson
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

FRIDAY 15 AUGUST 1884

Assigned

+ J. Philp & Co.

GLS149-0275

6608 glb

It is submitted that this vessel
is eligible to have the notification
LM 6.884 recorded the boilers being
subject to reworking as per tender

14/8/84

DO NOT CROSS THIS MARGIN



© 2019

Lloyd's Register
Foundation