

# REPORT of SURVEY for REPAIRS, &c.

THURS 25 FEB 1886

Received in London Office,

No. 4329

No. in Reg. Book. *968* on the *Iron S.S. "State of Pennsylvania"* Master *Mann* Date, First Survey *15<sup>th</sup> Feb* Last Survey *18<sup>th</sup> Feb* 1886

TONNAGE

NET *1543*

GROSS *2472*

UNDER DK. *1715*

Built at *Glasgow*

By whom *Lou. & Glas. Co. Ltd.* When *1873* 2

Owners *The State Steam Ship Co. (Lim.)* Port belonging to *Glasgow*

Owner's Address  
(if not already recorded in Appendix to Register Book.)

*If* Surveyed Afloat *or in Dry Dock* Name of Dock *Harbour* Destined Voyage *New York*

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins.  
(if these particulars are not yet recorded in the Register Book.)

Classed

Last Survey, No. *7045* Port *GL*

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) as painted on Ship } in salt water ft. ins. in fresh water ft. ins. *SS Co. 2-82*

REPAIRS, OR EXAMINATION AS PER RULE *Part B.B. No. 3.*

The lining of the after saloon, between the main and spar decks, and extending over 21 frame spaces on the starboard side and 22 ditto. on the port side - now stripped off; the iron work of the sides of the vessel there, cleaned, examined, found satisfactory, and recoated.

The Owners state that they intend to renew the boilers and to complete the B.B. No. 3. on the return of the vessel from her next voyage.

## PRESENT CONDITION OF THE

Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks and Stemson	Windlass & Capstan	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Pumps	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Cement (if Iron Ship)	Anchors No. of
Planksheers	Ditto ditto at other places	Caulking of Bot'm, D'k, & Wat'rways	Cables
Sheerstrakes	Keelsons	Copper, or Y.M. (State if on Felt.)	Hawsers & Warps
Topsides	Clamps & Shelves	When put on	Standing & Running Rigging
Wales			

Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Cargo & Main Hatchways Hatches

General Observations, Opinion as to Class, &c.:

The above remarks are respectfully submitted for the information of the Committee.

Entry Fee (if chargeable) per Scale I., Sec. 27. £ :  
 Same Fee (if chargeable) per Scale II., Sec. 27. £ :  
 Same Fee (per Section 28) ..... £ :  
 Damage Fee (if any) (per Sec. 28) ..... £ :  
 (If required) to be sent as per margin £ :  
 Travelling Expenses (if chargeable) ..... £ :  
 Second Surveyor's Fee (if any) ..... £ :

received by me, 188


Committee's Minute

FRIDAY 26 FEB 1886

Character assigned

Surveyor to Lloyd's Register of British & Foreign Shipping.

G. Stanbury



Lloyd's Register Foundation